OIL ANALYSIS REPORT

TOM HAMMERSLAG VOLVO PENTA 3950003841 - PORT IPS

Sample No: VPA049991

Oil Type: VOLVO PENTA GL-5 SAE 75W90

Cananala Numeria		VDA040004		
Sample Number		VPA049991 19 Mar 2024	VPA046783	
Sample Date Machine Hours		19 Mar 2024 430	06 Sep 2023 429	
Oil Hours		430 52	51	
		-		
Oil Changed Sample Status		Changed NORMAL	Not Changd ABNORMAL	
Sample Status		NORMAL	ADNORIVIAL	
OIL CONDITION				
Visc @ 40°C	cSt	108	107	
CONTAMINATION				
Water	%	NEG	▲ 0.283	
Silicon	ppm	<1	2	
Sodium	ppm	∎1	2	
Potassium	ppm	■ <1	3	
WEAR METALS				
PQ		15	16	
Iron	ppm	22	26	
Copper	ppm	3	2	
Lead	ppm	0	0	
Tin	ppm	0	0	
Aluminum	ppm	0	<1	
Chromium	ppm	0	 <1	
Molybdenum	ppm	0	0	
Nickel	ppm	0	0	
Titanium	ppm	0	0	
Silver	ppm	0	<1	
Manganese	ppm		1	
Vanadium	ppm	0	0	
ADDITIVES				
Calcium	ppm	0	6	
Magnesium	ppm	1 8	10	
Zinc	ppm	0	0	
Phosphorus	ppm	1237	1365	
Barium	ppm	0	0	
Boron	ppm	294	344	

YACHT BASIN MARINA 1866 OTTAWA BEACH RD HOLLAND, MI US 49424 Contact: OIL SAMPLE/PART kyle@yachtbasinmarina.com T: (616)786-2205

Diagnosis

Resample at the next service interval to monitor. Please note that this is a corrected copy for data entry updates.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP718610

 Unique No:
 10950545

 Signed:
 Doug Bogart

 Report Date:
 11 Apr 2024


 Contact/Location: OIL SAMPLE/PART - VP718610



OIL ANALYSIS REPORT







Contact/Location: OIL SAMPLE/PART - VP718610