



DON ANDERSON VOLVO PENTA 3940013912 - PORT IPS

Sample No: VPA059271

Oil Type: GEAR OIL SAE 75W90

CAMPLE INFORM	ATION			
SAMPLE INFORM	ATIUN			
Sample Number		VPA059271	VPA048251	
Sample Date		19 Mar 2024	22 Mar 2022	
Machine Hours		1382	1317	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	NORMAL	
OIL CONDITION				
Visc @ 40°C	cSt	111	□107	
CONTAMINATION	ı			
Water	%	△ 0.843	NEG	
Silicon	ppm	22	14	
Sodium	ppm	65	2 6	
Potassium	ppm	4	■0	
WEAR METALS				
PQ		■22	2 4	
Iron	ppm	229	173	
Copper	ppm	13	10	
Lead	ppm	<1	0	
Tin	ppm	<1	<1	
Aluminum	ppm	4	3	
Chromium	ppm	2	1	
Molybdenum	ppm	2	- <1	
Nickel	ppm	■3	1	
Titanium	ppm	<1	0	
Silver	ppm	<1	8	
Manganese	ppm	4	■3	
Vanadium	ppm	<1	0	
ADDITIVES				
Calcium	ppm	■ 26	5	
Magnesium	ppm	12	6	
Zinc	ppm	108	□ 66	
Phosphorus	ppm	1337	1427	
Barium	ppm	0	<u> </u>	
Boron	ppm	■ 305	289	

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW SEATTLE, WA US 98107 Contact: WILLOW YANARELLA service@coastalmarineengine.com T: (206)784-3703

Diagnosis

F: (206)784-8823

We advise that you check for the source of water entry. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Gear wear is indicated. There is a high concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP794951

 Unique No:
 10951805

 Signed:
 Jonathan Hester

 Report Date:
 02 Apr 2024

OIL ANALYSIS REPORT



