## **OIL ANALYSIS REPORT**

### WINDSERVE JOURNEY VOLVO PENTA 3950010402 - INBOARD 3 - STARBOARD IPS

Sample No: VPA057225

Oil Type: {unknown}

#### SAMPLE INFORMATION

Sample Number VPA057225						
Sample Date		21 Mar 2024				SENESCO MARINE- WINDSERVE MARINI
Machine Hours		364				10 MACNAUGHT ST
Oil Hours		0				NORTH KINGSTOWN, RI
Oil Changed		N/A				US 02852
Sample Status		NORMAL				Contact: CLAUDINO LUCIANO
			_			cluciano@senescomarine.com
OIL CONDITION						T:
Visc @ 40°C	cSt	97.9				F:
CONTAMINATION						Diagnosis
Water	%	Resample at the next service interval				
Silicon		NEG 6				to monitor.All component wear rate are normal. There is no indication o any contamination in the oil. The
Sodium	ppm					
	ppm	■4				
Potassium	ppm	5				condition of the oil is acceptable for the time in service.
WEAR METALS						the time in service.
PQ		22				
Iron	ppm	<b>46</b>				
Copper	ppm	5				
Lead	ppm	0				
Tin	ppm	0				
Aluminum	ppm	<1				
Chromium	ppm	0				
Molybdenum	ppm	0				
Nickel	ppm	0				
Titanium	ppm	0				
Silver	ppm	0				
Manganese	ppm	6				
Vanadium	ppm	0				
ADDITIVES						
Calcium	ppm	45				
Magnesium	ppm	976				
Zinc	ppm	15				
Phosphorus	ppm	1835				
Barium	ppm	0				
Boron	ppm	613				
20.011	PPIII	0.0				




Depot:VPSENNORUnique No:10966514Signed:Don BaldridgeReport Date:10 Apr 2024

Contact/Location: CLAUDINO LUCIANO - VPSENNOR

# **OIL ANALYSIS REPORT**



#### GRAPHS



Report Id: VPSENNOR [WUSCAR] 06141706 (Generated: 04/11/2024 08:29:00) Rev: 1

Contact/Location: CLAUDINO LUCIANO - VPSENNOR