



SURVEY JOHNSON SURVEY JOHNSON KOHLER 2318453 - GENSET

Sample No: VPA057336

Oil Type: DIESEL ENGINE OIL SAE 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA057336	 	
Sample Date		04 Apr 2024	 	
Machine Hours		1163	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	14.2	 	
Base Number (BN)	mg KOH/g	■9.3	 	
Oxidation (PA)	%	67	 	
CONTAMINATION				
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■ 0.1	 	
Nitration (PA)	%	53	 	
Sulfation (PA)	%	53	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■ 7	 	
Sodium	ppm	■ 2	 	
Potassium	ppm	2	 	
WEAR METALS				
Iron	ppm	2	 	
Copper	ppm	_ <1	 	
Lead	ppm	■0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	1	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	45	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	■<1	 	
Silver	ppm	■ 0	 	
Manganese	ppm	■<1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	1504	 	
Magnesium	ppm	■ 638	 	
Zinc	ppm	1249	 	
Phosphorus	ppm	995	 	
Barium	ppm	■0	 	
Boron	ppm	45	 	
	1-1			

Suncoast Diesel Marine Inc.

610 Mount Vernan St OLDSMAR, FL US 34677 Contact: MARK WARREN oldsmar@suncoastdmi.com T: (813)475-5942 F: (813)475-5943

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP945077

 Unique No:
 10966846

 Signed:
 Doug Bogart

 Report Date:
 09 Apr 2024

OIL ANALYSIS REPORT



