

OIL ANALYSIS REPORT

VOLVO PENTA

NORTHERN LIGHTS 6732-2573 1C - GENSET

Sample No: VPA047536

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

SAMPLE INFORMATION

Sample Number	VPA047536	---	---	---
Sample Date	04 Apr 2024	---	---	---
Machine Hours	1860	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

OIL CONDITION

Visc @ 100°C	cSt	█ 13.5	---	---	---
Base Number (BN)	mg KOH/g	█ 9.9	---	---	---
Oxidation (PA)	%	57	---	---	---

CONTAMINATION

Water	%	NEG	---	---	---
Soot %	%	█ 0.1	---	---	---
Nitration (PA)	%	43	---	---	---
Sulfation (PA)	%	51	---	---	---
Glycol	%	NEG	---	---	---
Fuel	%	< 1.0	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ < 1	---	---	---
Potassium	ppm	█ 0	---	---	---

WEAR METALS

Iron	ppm	█ 1	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ < 1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ < 1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 56	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	< 1	---	---	---

ADDITIVES

Calcium	ppm	█ 1017	---	---	---
Magnesium	ppm	█ 916	---	---	---
Zinc	ppm	█ 1193	---	---	---
Phosphorus	ppm	█ 987	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 5	---	---	---

Bay Marine Boatworks Inc.
310 West Cutting Blvd.
RICHMOND, CA
US 94804
Contact: David Vandervoort
max@baymarineboatworks.com
T:
F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: VP601779
Unique No: 10981638
Signed: Jonathan Hester
Report Date: 19 Apr 2024

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

