

OIL ANALYSIS REPORT



DAVID GRAY ZF 20160854 - INBOARD - PORT GEARBOX

Sample No: VPA054929
Oil Type: SHELL ROTELLA T 30

SAMPLE INFORMATION

Sample Number	VPA054929	---	---	---
Sample Date	19 Apr 2024	---	---	---
Machine Hours	294	---	---	---
Oil Hours	1	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	NORMAL	---	---	---

YACHT BASIN MARINA
1866 OTTAWA BEACH RD
HOLLAND, MI
US 49424
Contact: OIL SAMPLE/PART
kyle@yachtbasinmarina.com
T: (616)786-2205
F:

OIL CONDITION

Visc @ 40°C	cSt	█ 94.4	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 0	---	---	---

WEAR METALS

PQ		█ 27	---	---	---
Iron	ppm	█ 12	---	---	---
Copper	ppm	█ 54	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 119	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 1	---	---	---
Vanadium	ppm	█ 0	---	---	---

ADDITIVES

Calcium	ppm	█ 2811	---	---	---
Magnesium	ppm	█ 65	---	---	---
Zinc	ppm	█ 1208	---	---	---
Phosphorus	ppm	█ 1124	---	---	---
Barium	ppm	█ 2	---	---	---
Boron	ppm	█ 16	---	---	---

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP718610
Unique No: 10991721
Signed: Sean Felton
Report Date: 24 Apr 2024

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

