

OIL ANALYSIS REPORT

VOLVO PENTA

MARINE MAX VOLVO PENTA A727927 - PORT COOLANT

Sample No: VPA053455
Oil Type: VOLVO COOLANT VCS (YELLOW)

SAMPLE INFORMATION

Sample Number	VPA053455	---	---	---
Sample Date	18 Apr 2024	---	---	---
Machine Hours	445	---	---	---
Sample Status	NORMAL	---	---	---

COOLANT CONDITION

pH	Scale 0-14	■ 7.87	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 57.9	---	---	---
Freezing Point	°C	■ -52	---	---	---

CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

INTERSTATE POWERSYSTEMS

21568 HIGHVIEW AVE
LAKEVILLE, MN
US 55044

Contact: NICK BECK
nicholas.beck@istate.com
T: (952)854-2598
F: (952)854-1788

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

OIL ANALYSIS REPORT

GRAPHS

