

# OIL ANALYSIS REPORT

# VOLVO PENTA

## SOUTH PAW ZF SOUTH PAW - INBOARD (S/N NOT GIVEN) - PORT GEARBOX

Sample No: VPA044102

Oil Type: {unknown}

### SAMPLE INFORMATION

Sample Number	VPA044102	---	---	---
Sample Date	26 Apr 2024	---	---	---
Machine Hours	562	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

### BEST MARINE

24 RIVERVIEW AVE

TARRYTOWN, NY

US 10591

Contact: PETE ROESTENBERG

PETEMARINE27@OUTLOOK.COM

T: (516)807-5340

F:

### OIL CONDITION

Visc @ 40°C	cSt	█ 116	---	---	---
-------------	-----	-------	-----	-----	-----

### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 0	---	---	---

### WEAR METALS

PQ		█ 66	---	---	---
Iron	ppm	█ 71	---	---	---
Copper	ppm	█ 377	---	---	---
Lead	ppm	█ 3	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ 4	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	52	---	---	---
Nickel	ppm	█ 3	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	<1	---	---	---

### ADDITIVES

Calcium	ppm	3409	---	---	---
Magnesium	ppm	30	---	---	---
Zinc	ppm	1064	---	---	---
Phosphorus	ppm	1013	---	---	---
Barium	ppm	1	---	---	---
Boron	ppm	462	---	---	---

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal for OEM. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VPBESTAR

Unique No: 11008407

Signed: Doug Bogart

Report Date: 07 May 2024

# OIL ANALYSIS REPORT

# VOLVO PENTA

## GRAPHS

