

OIL ANALYSIS REPORT

VOLVO PENTA

MORTON VOLVO PENTA 3950001875 - PORT IPS

Sample No: VPA061580

Oil Type: GEAR OIL SAE 75W90

SAMPLE INFORMATION

Sample Number	VPA061580	---	---	---
Sample Date	07 May 2024	---	---	---
Machine Hours	918	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	ABNORMAL	---	---	---

OIL CONDITION

Visc @ 40°C	cSt	■ 106	---	---	---
-------------	-----	-------	-----	-----	-----

CONTAMINATION

Water	%	▲ 0.201	---	---	---
Silicon	ppm	■ 13	---	---	---
Sodium	ppm	■ 7	---	---	---
Potassium	ppm	■ 4	---	---	---

WEAR METALS

PQ		■ 22	---	---	---
Iron	ppm	■ 40	---	---	---
Copper	ppm	■ 12	---	---	---
Lead	ppm	■ 2	---	---	---
Tin	ppm	■ 2	---	---	---
Aluminum	ppm	■ 2	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 3	---	---	---
Nickel	ppm	■ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 4	---	---	---
Vanadium	ppm	<1	---	---	---

ADDITIVES

Calcium	ppm	■ 84	---	---	---
Magnesium	ppm	■ 29	---	---	---
Zinc	ppm	■ 214	---	---	---
Phosphorus	ppm	■ 1342	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 317	---	---	---

SUNCOAST DIESEL MARINE

6341 PORTER ROAD, SUITE 6
SARASOTA, FL
US 34240
Contact: JOSHUA
joshua@suncoastdmi.com
T: (941)342-0033
F: (941)342-0088

Diagnosis

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. Resample at the next service interval to monitor. All component wear rates are normal. There is a light concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot: VP705283
Unique No: 11019211
Signed: Doug Bogart
Report Date: 09 May 2024

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

