## **OIL ANALYSIS REPORT**

## WELSBERG C10703 VOLVO PENTA 5102074110J - MAIN COOLANT

Sample No: VPA061846

Oil Type: VOLVO COOLANT VCS (YELLOW)

### SAMPLE INFORMATION

Sample Number		VPA061846	 	
Sample Date		07 May 2024	 	
Machine Hours		1	 	
Sample Status		ABNORMAL	 	
COOLANT CONDITIO	DN			
рН	Scale 0-14	8.16	 	
Reserve Alkalinity	Scale 0-20		 	
Nitrites	ppm	<b>NT</b>	 	
Percentage Glycol	%	35.1	 	
Freezing Point	°C	<b>-3</b>	 	
CONTAMINATION				
Coolant Appearance		🔺 sediment	 	
Coolant Color		Yllow	 	

#### Walstrom Marine - 767948

OLVO ENTA

501 Bay Street HARBOR SPRINGS, MI US 49740 Contact: RICK HEINY rheiny@walstrom.com T:


## Diagnosis

We recommend drain/flush system, and refill with 50/50 antifreeze water mixture. Sediment present. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

# **OIL ANALYSIS REPORT**



### GRAPHS



Contact/Location: RICK HEINY - VP154879