



## ENOS VOLVO PENTA 7008458832 - DIESEL ENGINE

Sample No: VPA051240

Oil Type: DIESEL ENGINE OIL SAE 40

SAMPLE INFORMAT	TION			
Sample Number		VPA051240	 	
Sample Date		12 May 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>13.3</b>	 	
Base Number (BN)	mg KOH/g	<b>10.0</b>	 	
Oxidation (PA)	%	55	 	
CONTAMINATION				
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■0.2	 	
Nitration (PA)	%	43	 	
Sulfation (PA)	%	52	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■11	 	
Sodium	ppm	■0	 	
Potassium	ppm	<b>■</b> 3	 	
WEAR METALS				
Iron	ppm	<b>10</b>	 	
Copper	ppm	■ 19	 	
Lead	ppm	<b>■</b> <1	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	2	 	
Chromium	ppm	<1	 	
Molybdenum	ppm	<b>■</b> 65	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	<b>■&lt;1</b>	 	
Silver	ppm	<b>■</b> <1	 	
Manganese	ppm	<b>■</b> <1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	<b>1081</b>	 	
Magnesium	ppm	<b>916</b>	 	
Zinc	ppm	<b>1211</b>	 	
Phosphorus	ppm	<b>1109</b>	 	
Barium	ppm	<b>2</b>	 	
Boron	ppm	<b>0</b>	 	
201011	Lh			

## **MAKO MARINE**

117 HUDSON AVE
FREEPORT, NY
US 11520
Contact: PAUL FLOOD
makomarine@optonline.net
T: (516)378-7331
F: x:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP1134331Unique No:11022880Signed:Sean FeltonReport Date:14 May 2024

Contact/Location: PAUL FLOOD - VP1134331

## **OIL ANALYSIS REPORT**



