



## J163787331 VOLVO PENTA 3950004120 (S/N 395004120) - PORT IPS

Sample No: VPA051233
Oil Type: {unknown}

SAMPLE INFORM	ATION			
Sample Number		VPA051233	 	
Sample Date		12 May 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>106</b>	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	2	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	<b>0</b>	 	
WEAR METALS				
PQ		<b>15</b>	 	
Iron	ppm	<b>4</b>	 	
Copper	ppm	3	 	
Lead	ppm	0	 	
Tin	ppm	<1	 	
Aluminum	ppm	0	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	3	 	
Magnesium	ppm	0	 	
Zinc	ppm	0	 	
Phosphorus	ppm	1378	 	
Barium	ppm	0	 	
Boron	ppm	330	 	

## **MAKO MARINE**

117 HUDSON AVE FREEPORT, NY US 11520 Contact: PAUL FLOOD makomarine@optonline.net T: (516)378-7331

## Diagnosis

F: x:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP1134331Unique No:11023551Signed:Don BaldridgeReport Date:15 May 2024

## **OIL ANALYSIS REPORT**



