

OIL ANALYSIS REPORT

VOLVO PENTA

DON MEHRER 502993/8750 ZF 54141-E009 - PORT GEARBOX

Sample No: VPA053157

Oil Type: ATF

SAMPLE INFORMATION

Sample Number	VPA053157	---	---	---
Sample Date	15 May 2024	---	---	---
Machine Hours	1544	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	ABNORMAL	---	---	---

Endor Marine LLC - Coastal Marine - 152124
4300 11th Ave. NW
SEATTLE, WA
US 98107
Contact: WILLOW YANARELLA
service@coastalmarineengine.com
T: (206)784-3703
F: (206)784-8823

OIL CONDITION

Visc @ 40°C	cSt	■ 28.8	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 24	---	---	---
Sodium	ppm	■ 6	---	---	---
Potassium	ppm	■ 4	---	---	---

WEAR METALS

PQ		■ 44	---	---	---
Iron	ppm	■ 122	---	---	---
Copper	ppm	■ 112	---	---	---
Lead	ppm	▲ 128	---	---	---
Tin	ppm	■ 5	---	---	---
Aluminum	ppm	■ 3	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ 2	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	■ 1	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	■ 66	---	---	---
Magnesium	ppm	■ 2	---	---	---
Zinc	ppm	■ 23	---	---	---
Phosphorus	ppm	■ 173	---	---	---
Barium	ppm	■ 8	---	---	---
Boron	ppm	■ 91	---	---	---

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The lead level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP794951
Unique No: 11034870
Signed: Don Baldrige
Report Date: 21 May 2024

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

