

# OIL ANALYSIS REPORT

**VOLVO  
PENTA**

**SBM MARINE SERVICES VOLVO PENTA 7008553584 - PORT COOLANT**

**Sample No:** VPA062976

**Oil Type:** VOLVO COOLANT VCS (YELLOW)

## SAMPLE INFORMATION

Sample Number	VPA062976	---	---	---
Sample Date	22 May 2024	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

## COOLANT CONDITION

pH	Scale 0-14	■ 8.22	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 37.9	---	---	---
Freezing Point	°C	■ -7	---	---	---

## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

### RELIABLE SNOWPLOWING

3820 ROBERTS RIDGE

AKRON, OH

US 44333

Contact: NORM DETRICK

normdetrick@reliablesnowplowing.net

T: (216)905-7118

F:

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. Appearance is acceptable. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** VPRELAKR

**Unique No:** 11046896

**Signed:** Doug Bogart

**Report Date:** 30 May 2024

# OIL ANALYSIS REPORT



## GRAPHS

