## **OIL ANALYSIS REPORT**

### 3870/44-19 FISCHER PANDA 2005603 - CENTER GENSET

Sample No: VPA054158

Oil Type: SHELL 15W40

#### SAMPLE INFORMATION VPA054158 Sample Number Sample Date 24 May 2024 Machine Hours 0 0 **Oil Hours** Oil Changed Changed NORMAL Sample Status **OIL CONDITION** F: 13.5 Visc @ 100°C cSt Base Number (BN) mg KOH/g 9.6 Oxidation (PA) % 56 CONTAMINATION % NEG Water % Soot % 0.3 Nitration (PA) % 48 % Sulfation (PA) 53 Glycol % NEG Fuel % <1.0 Silicon 11 ppm Sodium 1 ppm Potassium 5 ppm WEAR METALS Iron 6 ppm **||** <1 Copper ppm Lead 0 🔲 ppm Tin 0 ppm Aluminum ppm 2 Chromium ppm | <1 2 Molybdenum ppm Nickel 0 ppm Titanium ppm 0 0 Silver ppm Manganese ■ <1 ppm Vanadium 0 ppm **ADDITIVES** Calcium 2464 ppm Magnesium 33 ppm Zinc ppm 1137 Phosphorus ppm 981 Barium 0 ppm Boron ppm **181**



**GRAND BANKS** 

450 SW SALEM RD STUART, FL US 34994 Contact: ROBERT ANTONA roberta@gbmarinegroup.com T: (609)384-5290

#### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP531377

 Unique No:
 11060587

 Signed:
 Don Baldridge

 Report Date:
 05 Jun 2024

Report Id: VP531377 [WUSCAR] 06198464 (Generated: 06/05/2024 21:16:08) Rev: 1

Contact/Location: ROBERT ANTONA - VP531377

# **OIL ANALYSIS REPORT**



#### GRAPHS

