



JUAN VALDEZ VOLVO PENTA 22775506 - INBOARD - PORT GEARBOX

Sample No: VPA053315
Oil Type: DEXRON III

| SAMPLE INFORMA | ATION | | | |
|----------------|-------|-------------|------|--|
| Sample Number | | VPA053315 | | |
| Sample Date | | 06 Jun 2024 | | |
| Machine Hours | | 7 | | |
| Oil Hours | | 7 | | |
| Oil Changed | | Not Changd | | |
| Sample Status | | NORMAL | | |
| | | HORWAL | | |
| OIL CONDITION | | | | |
| Visc @ 40°C | cSt | ■37.0 | | |
| CONTAMINATION | | | | |
| Water | % | NEG | | |
| Silicon | ppm | ■13 | | |
| Sodium | ppm | 2 | | |
| Potassium | ppm | <u> </u> | | |
| | pp | | | |
| WEAR METALS | | | | |
| PQ | | ■30 | | |
| Iron | ppm | 47 | | |
| Copper | ppm | ■38 | | |
| Lead | ppm | ■ 0 | | |
| Tin | ppm | ■ <1 | | |
| Aluminum | ppm | ■ 2 | | |
| Chromium | ppm | ■ <1 | | |
| Molybdenum | ppm | ■ 0 | | |
| Nickel | ppm | ■0 | | |
| Titanium | ppm | 0 | | |
| Silver | ppm | 0 | | |
| Manganese | ppm | 1 | | |
| Vanadium | ppm | 0 | | |
| ADDITIODA | | | | |
| Calcium | ppm | 42 | | |
| Magnesium | ppm | 2 | | |
| Zinc | ppm | 22 | | |
| Phosphorus | ppm | 262 | | |
| Barium | ppm | 6 | | |
| Boron | ppm | 158 | | |

CY MARINE LLC

3821 NW 135th ST, SUITE F OPA LOCKA, FL US 33054 Contact: CAMERON MEDINA cymarinellc@gmail.com T: (954)702-8096 F: x:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VPCYMPOMUnique No:11070512Signed:Don BaldridgeReport Date:10 Jun 2024

OIL ANALYSIS REPORT



