

# OIL ANALYSIS REPORT

# VOLVO PENTA

**WEBER VOLVO PENTA 3940018816 - PORT IPS**

**Sample No:** VPA062747

**Oil Type:** {unknown}

## SAMPLE INFORMATION

Sample Number	VPA062747	---	---	---
Sample Date	11 Jun 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**Harry's Marine Service LLC**

1141 N. Citrus St.

Orange, CA

US 92887

Contact: TARAH AULD

info@harrismarine.com

T: (714)771-7899

F:

## OIL CONDITION

Visc @ 40°C	cSt	█ 105.7	---	---	---
-------------	-----	---------	-----	-----	-----

## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 8	---	---	---
Sodium	ppm	█ 6	---	---	---
Potassium	ppm	█ 1	---	---	---

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

## WEAR METALS

PQ		█ 16	---	---	---
Iron	ppm	█ 20	---	---	---
Copper	ppm	█ 6	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	█ <1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---

## ADDITIVES

Calcium	ppm	0	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	5	---	---	---
Phosphorus	ppm	1181	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	344	---	---	---

**Depot:** VP867279

**Unique No:** 11075553

**Signed:** Doug Bogart

**Report Date:** 13 Jun 2024

# OIL ANALYSIS REPORT

# VOLVO PENTA

## GRAPHS

