



## VRABECK VRABECK VOLVO PENTA 3940023886 - IPS

Sample No: VPA054992
Oil Type: {unknown}

SAMPLE INFORMAT	TION			
Sample Number		VPA054992	 	
Sample Date		20 Jun 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>113.7</b>	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	<b>11</b>	 	
Sodium	ppm	<b>6</b>	 	
Potassium	ppm	<b>2</b>	 	
WEAR METALS				
PQ		<b>19</b>	 	
Iron	ppm	<b>■</b> 96	 	
Copper	ppm	■4	 	
Lead	ppm	<b>■&lt;1</b>	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>■</b> 3	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	<b>1</b>	 	
Titanium	ppm	<b>■&lt;1</b>	 	
Silver	ppm	<1	 	
Manganese	ppm	5	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	0	 	
Magnesium	ppm	4	 	
Zinc	ppm	21	 	
Phosphorus	ppm	531	 	
Barium	ppm	1	 	
Boron	ppm	25	 	

## Harry`s Marine Service LLC

1141 N. Citrus St.
Orange, CA
US 92887
Contact: TARAH AULD
info@harrysmarine.com
T: (714)771-7899
F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP867279Unique No:11098530Signed:Doug BogartReport Date:25 Jun 2024

## **OIL ANALYSIS REPORT**



