



OWYG R0147737 VOLVO PENTA 3950006041 - PORT IPS

Sample No: VPA060691
Oil Type: {unknown}

SAMPLE INFORMA	ATION			
Sample Number		VPA060691	 	
Sample Date		20 Jun 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
Sample Status		HORWAL		
OIL CONDITION				
Visc @ 40°C	cSt	■ 103	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	1125	 	
Sodium	ppm	■ <1	 	
Potassium	ppm	= <1	 	
	1.1.	_		
WEAR METALS				
PQ		17	 	
Iron	ppm	■ 36	 	
Copper	ppm	■ 3	 	
Lead	ppm	■ 0	 	
Tin	ppm	■0	 	
Aluminum	ppm	■ <1	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	■0	 	
Titanium	ppm	■ 0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITIDES				
Calcium	ppm	9	 	
Magnesium	ppm	21	 	
Zinc	ppm	4	 	
Phosphorus	ppm	1374	 	
Barium	ppm	0	 	
Boron	ppm	299	 	

ONE WATER YACHT

3201 W STATE RD 84 FR LAUDERDALE, FL US 33312 Contact: ANTHONY VIGLIOTTI avigliotti@owyg.com T: (954)292-4857

Diagnosis

F:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP1134827Unique No:11099770Signed:Angela BorellaReport Date:28 Jun 2024

OIL ANALYSIS REPORT



