



BOUVIN VOLVO PENTA 3194010561 - PORT IPS

Sample No: VPA051142
Oil Type: {unknown}

SAMPLE INFORMA	ATION			
Sample Number		VPA051142	 	
Sample Date		25 Jun 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	106	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	6	 	
Sodium	ppm	2	 	
Potassium	ppm	1	 	
WEAR METALS				
PQ		21	 	
Iron	ppm	■ 9	 	
Copper	ppm	4	 	
Lead	ppm	■<1	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	■3	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	2	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	■ <1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	94	 	
Magnesium	ppm	6	 	
Zinc	ppm	37	 	
Phosphorus	ppm	1437	 	
Barium	ppm	0	 	
Boron	ppm	315	 	

MAKO MARINE

117 HUDSON AVE
FREEPORT, NY
US 11520
Contact: PAUL FLOOD
makomarine@optonline.net
T: (516)378-7331
F: x:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP1134331Unique No:11100776Signed:Doug BogartReport Date:28 Jun 2024

Contact/Location: PAUL FLOOD - VP1134331

OIL ANALYSIS REPORT



