OIL ANALYSIS REPORT

EMERALD PACIFIC YACHTS SR00100071 VOLVO PENTA 3950007715 - PORT IPS

Sample No: VPA054827

Oil Type: {unknown}

SAMPLE INFORMATION VPA054827 Sample Number Pacific Power Group - VP981534 Sample Date 24 Jun 2024 7215 S 228th St Machine Hours 301 Kent, WA 0 **Oil Hours** US 98032 N/A Oil Changed Contact: PAT RYAN NORMAL Sample Status pryan@pacificpowergroup.com T: (253)520-5163 **OIL CONDITION** F: Visc @ 40°C cSt 104 Diagnosis CONTAMINATION Resample at the next service interval % Water NEG to monitor.All component wear rates Silicon ppm 3 are normal. There is no indication of Sodium 2 ppm any contamination in the fluid. The Potassium ppm 3 condition of the fluid is acceptable for the time in service. WEAR METALS PO 20 26 Iron ppm Copper 2 ppm Lead **||** <1 ppm Tin ■ <1 ppm 3 Aluminum ppm Chromium ■<1 ppm Molybdenum <1 ppm Nickel ppm <1 Titanium **||** <1 ppm Silver <1 ppm 2 Manganese ppm Vanadium <1 ppm **ADDITIVES** Calcium 3 ppm 156 Magnesium ppm Zinc ppm 5 1451 Phosphorus ppm Barium <1 ppm 333 Boron ppm

 Depot:
 VP99031103

 Unique No:
 11103032

 Signed:
 Don Baldridge


 Report Date:
 02 Jul 2024



OIL ANALYSIS REPORT



GRAPHS



Report Id: VP99031103 [WUSCAR] 06224835 (Generated: 07/02/2024 19:58:38) Rev: 1

Contact/Location: PAT RYAN - VP99031103