



ALASKA LUXURY TOURS VOLVO PENTA A 1204658 - PORT DIESEL ENGINE

Sample No: VPA036461 **Oil Type:** 15W40 CK-4

SAMPLE INFORMAT	TION			
		\/D4026464	\ (D.4.02.6720	
Sample Number		VPA036461	VPA036730	
Sample Date		02 Jul 2024	29 May 2024	
Machine Hours		445	199	
Oil Hours		246	199	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL CONDITION				
Visc @ 100°C	cSt	14.0	□13.9	
Base Number (BN)	mg KOH/g	10.1	9.9	
Oxidation (PA)	%	56	58	
CONTAMINATION				
	0.4			
Water	%	NEG	NEG	
Soot %	%	■ 0.5	0.2	
Nitration (PA)	%	54	49	
Sulfation (PA)	%	53	52	
Glycol	%	NEG	NEG	
Fuel	%	<1.0	<1.0	
Silicon	ppm	■9	□ 24	
Sodium	ppm	2	5	
Potassium	ppm	■ <1	□3	
WEAR METALS				
Iron	ppm	2 4	2 5	
Copper	ppm	■9	□18	
Lead	ppm	■2	□3	
Tin	ppm	1	4	
Aluminum	ppm	■3	8	
Chromium	ppm	<u>2</u>	3	
Molybdenum	ppm	■63	6 3	
Nickel		2	4	
Titanium	ppm	0	4 <1	
Silver	ppm	0	0	
	ppm	<1	<1	
Manganese	ppm	_	_	
Vanadium	ppm	0	0	
ADDITIVES				
Calcium	ppm	1263	1245	
Magnesium	ppm	1069	961	
Zinc	ppm	1421	□1264	
Phosphorus	ppm	1185	998	
Barium	ppm	■0	0	
Boron	ppm	2	1 0	
	1 10			

Sundance Mfg Inc

570 N.E. Tomahawk Isl. Dr. Portland, OR US 97217 Contact: DAVID TAYLOR david@sundanceyachts.com T: (360)630-1495 F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP154394Unique No:11114466Signed:Sean FeltonReport Date:10 Jul 2024

Contact/Location: DAVID TAYLOR - VP154394

OIL ANALYSIS REPORT



