## **OIL ANALYSIS REPORT**

### QBCH VOLVO PENTA 3940013386 - STARBOARD IPS

Sample No: VPA062364 Oil Type: {unknown}

•	 (unition

#### SAMPLE INFORMATION Sample Number VPA062364 **Qualtiy Boats** 27 Jun 2024 Sample Date 3340 Placida Road Machine Hours 0 ENGLEWOOD, FL 43 **Oil Hours** US 34224 Oil Changed Not Changd Contact: JASON HOGAN NORMAL Sample Status JHOGAN@OUALITYBOATS.COM T: **OIL CONDITION** F: Visc @ 40°C cSt 103 Diagnosis CONTAMINATION Resample at the next service interval % Water NEG to monitor.All component wear rates Silicon ppm 12 are normal. There is no indication of Sodium 27 ppm any contamination in the oil. The Potassium ppm 2 condition of the oil is acceptable for the time in service. WEAR METALS PO 16 244 Iron ppm Copper ppm 29 Lead 0 ppm 0 🔲 Tin ppm 2 Aluminum ppm Chromium ppm 2 Molybdenum <1 ppm Nickel ppm 2 Titanium 0 ppm Silver <1 ppm 6 Manganese ppm Vanadium 0 ppm **ADDITIVES** 6 Calcium ppm 34 Magnesium ppm Zinc ppm 52 1534 Phosphorus ppm Barium 0 ppm Boron ppm 317



 Depot:
 VP414527

 Unique No:
 11117041

 Signed:
 Don Baldridge


 Report Date:
 13 Jul 2024

 Contact/Location: JASON HOGAN - VP414527

# **OIL ANALYSIS REPORT**



### GRAPHS



Report Id: VP414527 [WUSCAR] 06233548 (Generated: 07/13/2024 12:04:44) Rev: 1

Contact/Location: JASON HOGAN - VP414527