




OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id
HANSEN 1443-DT GEARBOX

Component
Gearbox
Fluid

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the component.

Fluid Condition

The condition of oil is suitable for further service.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WCI006600	WCI006674	WCI2015608
Sample Date	Client Info		06 Jan 2003	17 Dec 2002	02 Oct 2002
Machine Age	mths	Client Info	0	0	0
Oil Age	mths	Client Info	17	16	14
Oil Changed	Client Info		Not Changd	Not Changd	Not Changd
Sample Status			NORMAL	NORMAL	ABNORMAL

CONTAMINATION



	method	limit/base	current	history1	history2
Water	WC Method		NEG	NEG	NEG

SAMPLE IMAGES






	method	limit/base	current	history1	history2
Color			<i>no image</i>	<i>no image</i>	<i>no image</i>
Bottom			<i>no image</i>	<i>no image</i>	<i>no image</i>



OIL ANALYSIS REPORT



GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC1006600
Lab Number : 00412817
Unique Number : 1506140
Test Package : IND 2
Received : 13 Jan 2003
Tested : 14 Jan 2003
Diagnosed :

CARGILL OILSEEDS-WICHITA
 1408 N BARWISE
 WICHITA, KS
 US 67214
 Contact: GERRY THIBODEAU
 gerry_thibodeau@cargill.com
 T: (316)292-2742
 F: (316)292-2244

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)