

# **OIL ANALYSIS REPORT**

#### Area Hydraulics Machine Id PRESS #2

#### Component Hydraulic System

## SUNOCO SUNVIS 846 ISO 46 (550 GAL)

### DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

### Contamination

The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

### Fluid Condition

The condition of oil is suitable for further service.

Sample Rating Trend




NORMAL

## 1992 Mar/1993 Oct/993 Mar/1994 Apr/1997 Jul/1998 Feb2000 Jul/2003

SAMPLE INFORM	<b>IATION</b>	method	limit/base	current	history1	history2
Sample Number		Client Info		WC22036145	WC23001381	WC23001265
Sample Date		Client Info		26 Oct 2004	29 Apr 2004	29 Jan 2004
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES	6	method	limit/base	current	history1	history2
Color						no image
Bottom						no image



# **OIL ANALYSIS REPORT**



To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Contact/Location: Jim Smith - POLOAK

Detroit,

US 76100

T: (311)555-1212

F: (311)555-1313

Feb22/00

20

.74

20

19

18

1SO 4406:1999 Cle

15 5

14

13

Code