




OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Area
Hydraulics
 Machine Id
PRESS #2

Component
Hydraulic System
 Fluid

SUNOCO SUNVIS 846 ISO 46 (550 GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

Fluid Condition

The condition of oil is suitable for further service.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC22038074	WC22036145	WC23001381
Sample Date	Client Info		20 Jan 2005	26 Oct 2004	29 Apr 2004
Machine Age	hrs	Client Info	0	0	0
Oil Age	hrs	Client Info	0	0	0
Oil Changed	Client Info		N/A	N/A	N/A
Sample Status			NORMAL	NORMAL	NORMAL

CONTAMINATION


	method	limit/base	current	history1	history2
Water	WC Method		NEG	NEG	NEG

SAMPLE IMAGES






	method	limit/base	current	history1	history2
Color					
Bottom					



OIL ANALYSIS REPORT



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC22038074
Lab Number : 01178790
Unique Number : 1916965
Test Package : IND 2
Received : 28 Jan 2005
Tested : 31 Jan 2005
Diagnosed :

ABC Manufacturing
 555 NORTH SERVICE ROAD EAST
 Detroit,
 US 76100
 Contact: Jim Smith
 jim.smith@abcmanufacturing.com
 T: (311)555-1212
 F: (311)555-1313

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.