




OIL ANALYSIS REPORT

Area
Hydraulics
 Machine Id
PRESS #25
 Component
Hydraulic System
 Fluid
SUNOCO SUNVIS 868 ISO 68 (--- LTR)

Sample Rating Trend



NORMAL



DIAGNOSIS

Recommendation
 Resample at the next service interval to monitor.

Wear
 All component wear rates are normal.

Contamination
 The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

Fluid Condition
 The condition of oil is suitable for further service.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC22038065	WC22036135	---
Sample Date	Client Info		25 Jan 2005	26 Oct 2004	---
Machine Age	hrs	Client Info	0	0	---
Oil Age	hrs	Client Info	0	0	---
Oil Changed	Client Info		N/A	N/A	---
Sample Status			NORMAL	ABNORMAL	---

CONTAMINATION



	method	limit/base	current	history1	history2
Water	WC Method		NEG	NEG	---

SAMPLE IMAGES






	method	limit/base	current	history1	history2
Color					no image
Bottom					no image



OIL ANALYSIS REPORT



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC22038065
Lab Number : 01178796
Unique Number : 1916971
Test Package : IND 2
Received : 28 Jan 2005
Tested : 31 Jan 2005
Diagnosed :

ABC Manufacturing
 555 NORTH SERVICE ROAD EAST
 Detroit, US 76100
 Contact: Jim Smith
 jim.smith@abcmanufacturing.com
 T: (311)555-1212
 F: (311)555-1313

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.