



PROBLEM SUMMARY


PHR-G2-TUBR

Component Bearing Fluid MOBIL DTE OIL HVY MEDIUM (--- GAL)

COMPONENT CONDITION SUMMARY







RECOMMENDATION

We recommend you service the filters on this component. Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS

Sample Status		ATTENTION	ATTENTION	ATTENTION
Particles >4µm	ASTM D7647 >10000	🔺 15481	<u> </u>	🔺 10363
Oil Cleanliness	ISO 4406 (c) >20/18/1	4 🔺 21/18/14	1 21/18/13	21/16/12

Customer Id: NEWSTJ Sample No.: WC0316829 Lab Number: 02332586 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter	MISSED	Oct 21 2020	?	We recommend you service the filters on this component.			
Information Required	MISSED	Oct 21 2020	?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.			
Check Fluid Source	MISSED	Oct 21 2020	?	Confirm the source of the lubricant being utilized for top-up/fill.			

HISTORICAL DIAGNOSIS

27 Sep 2019 Diag: Kevin Marson

We recommend you service the filters on this component. Confirm the source of the lubricant being utilized for topup/fill. Resample at the next service interval to monitor. The fluid was specified as MOBIL DTE OIL HVY MEDIUM, however, a fluid match indicates that this fluid is ISO 68 R&O Hydraulic Oil. Please confirm the oil type and grade on your next sample. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report

09 Jan 2019 Diag: Wes Davis

We recommend you service the filters on this component. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend

Machine Id PHR-G2-TUBR

Component Bearing Fluid MOBIL DTE OIL HVY MEDIUM (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear


All component wear rates are normal.

Contamination

There is a light amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0316829	WC0299337	WC985147
Sample Date		Client Info		13 Jan 2020	27 Sep 2019	09 Jan 2019
Machine Age	days	Client Info		0	0	0
Oil Age	days	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	ATTENTION	ATTENTION
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		5	8	9
Iron	ppm	ASTM D5185(m)	>63	2	2	2
Chromium	ppm	ASTM D5185(m)		0	0	0
Nickel	ppm	ASTM D5185(m)		<1	<1	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>161	<1	<1	<1
Copper	ppm	ASTM D5185(m)	>13	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>27	5	4	4
Antimony	ppm	ASTM D5185(m)		<1	<1	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		0	0	0
Barium	ppm	ASTM D5185(m)		<1	<1	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	<1
Magnesium	ppm	ASTM D5185(m)		<1	<1	0
Calcium	ppm	ASTM D5185(m)		<1	<1	<1
Phosphorus	ppm	ASTM D5185(m)		2	1	2
Zinc	ppm	ASTM D5185(m)		3	3	3
Sulfur	ppm	ASTM D5185(m)		1992	2036	2112
Lithium	ppm	ASTM D5185(m)		<1	<1	0
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>12	0	0	<1
Sodium	ppm	ASTM D5185(m)		0	0	0
Potassium	ppm	ASTM D5185(m)	>20	0	<1	0





0


OIL ANALYSIS REPORT


method

FLUID CLEANLINESS









Particles >4µm		ASTM D7647	>10000	🔺 15481	🔺 17476	10363
Particles >6µm		ASTM D7647	>2500	1606	1477	352
Particles >14µm		ASTM D7647	>160	101	44	21
Particles >21µm		ASTM D7647	>40	32	11	8
Particles >38µm		ASTM D7647	>10	2	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>20/18/14	A 21/18/14	1 /18/13	▲ 21/16/12
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		0.097	0.105	0.142
VISUAL		method	limit/base	current	history1	history2
				oarront		,
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
	scalar scalar					
White Metal		Visual*	NONE	NONE	NONE	NONE
White Metal Yellow Metal	scalar	Visual* Visual*	NONE NONE	NONE NONE	NONE	NONE
White Metal Yellow Metal Precipitate	scalar scalar	Visual* Visual* Visual*	NONE NONE NONE	NONE NONE NONE	NONE NONE NONE	NONE NONE NONE
White Metal Yellow Metal Precipitate Silt	scalar scalar scalar	Visual* Visual* Visual* Visual*	NONE NONE NONE	NONE NONE NONE NONE	NONE NONE NONE NONE	NONE NONE NONE NONE
White Metal Yellow Metal Precipitate Silt Debris	scalar scalar scalar scalar	Visual* Visual* Visual* Visual* Visual*	NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE NONE NONE	NONE NONE NONE NONE
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt	scalar scalar scalar scalar scalar	Visual* Visual* Visual* Visual* Visual* Visual*	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar scalar scalar	Visual* Visual* Visual* Visual* Visual* Visual* Visual*	NONE NONE NONE NONE NONE NORML	NONE NONE NONE NONE NONE NORE	NONE NONE NONE NONE NONE NORE	NONE NONE NONE NONE NONE NORE
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar scalar scalar scalar	Visual* Visual* Visual* Visual* Visual* Visual* Visual* Visual*	NONE NONE NONE NONE NONE NORML NORML	NONE NONE NONE NONE NONE NORML NORML	NONE NONE NONE NONE NONE NORML NORML	NONE NONE NONE NONE NONE NORML NORML

limit/base

current

FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	65.1	69.3	68.9	68.9
SAMPLE IMAC	GES	method	limit/base	current	history1	history2



history1

history2

Bottom

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0316829 Received : 17 Jan 2020 : 02332586 Diagnosed : 21 Jan 2020 Diagnostician : Kevin Marson Test Package : IND 2 (Additional Tests: PRTCOUNT)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

NEWFOUNDLAND POWER INC. 50 DUFFY PLACE, PO BOX 8910 ST. JOHNS, NL CA A1B 3P6 Contact: Paul Martin pmartin@newfoundlandpower.com Т:

F: (709)737-2926