



OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Area
DOMTAR
 Machine Id
7381
 Component
Diesel Engine
 Fluid
 {not provided} (--- LTR)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Wear

{not applicable}

Contamination

{not applicable}

Fluid Condition

{not applicable}

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		PP	---	---
Sample Date	Client Info		18 Apr 2023	---	---
Machine Age	hrs	Client Info	18772	---	---
Oil Age	hrs	Client Info	0	---	---
Oil Changed		Client Info	N/A	---	---
Sample Status			NORMAL	---	---

CONTAMINATION

	method	limit/base	current	history1	history2
Fuel	WC Method	>5	<1.0	---	---
Glycol	WC Method		NEG	---	---



VISUAL

	method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	---	---
Yellow Metal	scalar	Visual*	NONE	---	---
Precipitate	scalar	Visual*	NONE	---	---
Silt	scalar	Visual*	NONE	---	---
Debris	scalar	Visual*	NONE	---	---
Sand/Dirt	scalar	Visual*	NONE	---	---
Appearance	scalar	Visual*	NORML	---	---
Odor	scalar	Visual*	NORML	---	---
Emulsified Water	scalar	Visual*	NEG	---	---
Free Water	scalar	Visual*	NEG	---	---



OIL ANALYSIS REPORT

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PP **Received** : 26 Apr 2023
Lab Number : 02553560 **Diagnosed** : 28 Apr 2023
Unique Number : 5566575 **Diagnostician** : Kevin Marson
Test Package : TEST (Additional Tests: FT-IR, ICP, KV100, Spat)

WEARCHECK CANADA INC.
 C8-1175 Appleby Line
 BURLINGTON, ON
 CA L7L 5H9
 Contact: Dorian Anderson
 dorian.anderson@wearcheck.com
 T:
 F: (905)569-8605

*To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.*