


OIL ANALYSIS REPORT

Sample Rating Trend







Machine Id **50043908**

Component

Starboard Transmission (Manual)

SHELL ROTELLA T4 15W40 (--- LTR)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the fluid.


Fluid Condition

Viscosity of sample indicates oil is within SAE 30 range, advise investigate. The condition of the fluid is acceptable for the time in service.

				May2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WA0019678		
Sample Date		Client Info		15 May 2023		
Machine Age	hrs	Client Info		602		
Oil Age	hrs	Client Info		115		
Oil Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>200	11		
Chromium	ppm	ASTM D5185(m)	>5	0		
Nickel	ppm	ASTM D5185(m)	>5	<1		
Titanium	ppm	ASTM D5185(m)		5		
Silver	ppm	ASTM D5185(m)	>7	0		
Aluminum	ppm	ASTM D5185(m)	>25	4		
Lead	ppm	ASTM D5185(m)	>45	3		
Copper	ppm	ASTM D5185(m)	>225	25		
Tin	ppm	ASTM D5185(m)	>10	<1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		<1		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		149		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		10		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)		213		
Calcium	ppm	ASTM D5185(m)		2092		
Phosphorus	ppm	ASTM D5185(m)		974		
Zinc	ppm	ASTM D5185(m)		1031		
Sulfur	ppm	ASTM D5185(m)		3544		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>125	3		
Sodium	ppm	ASTM D5185(m)		4		
Potassium	ppm	ASTM D5185(m)	>20	4		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
Emulsified Water	scalar	Visual*	>0.1	NEG		
			-			
Free Water	scalar	Visual*		NEG		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number

Test Package : MOB 1

: WA0019678 : 02559029 : 5580069

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 23 May 2023 Diagnosed

: 24 May 2023 Diagnostician : Kevin Marson

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

CCGS LA POILE BAY

21 LOWER WARREN STREET LOUISBOURG, NS CA B1L 1B5

Contact: Service Manager spindrifteng.ccgs@dg-mpo.gc.ca T: (902)733-3700 F: