




OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Area
GENNEP
 Machine Id
SR19566
 Component
Diesel Fuel
 Fluid
DIESEL FUEL No. 2 (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Corrosion

{not applicable}

Contaminants

{not applicable}

Fuel Condition

{not applicable}

SAMPLE INFORMATION


method	limit/base	current	history1	history2
Sample Number	Client Info	WC0782392	---	---
Sample Date	Client Info	09 Aug 2023	---	---
Machine Age	hrs Client Info	0	---	---
Sample Status		NORMAL	---	---

SAMPLE IMAGES

method	limit/base	current	history1	history2
Color		<i>no image</i>	<i>no image</i>	<i>no image</i>
Bottom		<i>no image</i>	<i>no image</i>	<i>no image</i>



OIL ANALYSIS REPORT



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0782392
Lab Number : 02575275
Unique Number : 5620326
Test Package : TEST (Additional Tests: Cetane, GCD, SPECGRAVITY)

Received : 10 Aug 2023
Diagnosed : 18 Oct 2023
Diagnostician : Kevin Marson

*To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.*

WEARCHECK CANADA INC.
 C8-1175 Appleby Line
 BURLINGTON, ON
 CA L7L 5H9
 Contact: Dorian Anderson
 dorian.anderson@wearcheck.com
 T:
 F: (905)569-8605