


# **OIL ANALYSIS REPORT**

Sample Rating Trend



NORMAL



Machine Id 935310256

Component

Swing Drive

Fluid

GEAR OIL ISO 220 (--- GAL)

### DIAGNOSIS

## Recommendation

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the oil


## **Fluid Condition**

The condition of the oil is acceptable for the time in service.

				Aug2023		
SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0811312		
Sample Date		Client Info		16 Aug 2023		
Machine Age	hrs	Client Info		2000		
Oil Age	hrs	Client Info		1000		
Oil Changed	1113	Client Info		Not Changd		
Sample Status		Ollerit IIIIO		NORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>400	148		
Chromium	ppm	ASTM D5185(m)		1		
Nickel		ASTM D5185(m)	>10	<1		
Titanium	ppm	ASTM D5185(m)	>10	0		
Silver	ppm	ASTM D5185(III) ASTM D5185(m)		0		
	ppm	. ,	. 05			
Aluminum	ppm	ASTM D5185(m)	>25	<1		
Lead	ppm	ASTM D5185(m)	>50	<1		
Copper	ppm	ASTM D5185(m)	>200	4		
Tin	ppm	ASTM D5185(m)	>10	<1		
Antimony	ppm	ASTM D5185(m)	>5	0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	50	14		
Barium	ppm	ASTM D5185(m)	15	2		
Molybdenum	ppm	ASTM D5185(m)	15	0		
Manganese	ppm	ASTM D5185(m)		4		
Magnesium	ppm	ASTM D5185(m)	50	<1		
Calcium	ppm	ASTM D5185(m)	50	3		
Phosphorus	ppm	ASTM D5185(m)	350	448		
Zinc	ppm	ASTM D5185(m)	100	14		
Sulfur	ppm	ASTM D5185(m)	12500	5458		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	<1		
Sodium	ppm	ASTM D5185(m)		2		
Potassium	ppm	ASTM D5185(m)	>20	<1		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	VLITE		
Debris	scalar	Visual*	NONE	VLITE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
Emulsified Water	scalar	Visual*	>0.2	NEG		
			<b>⊅</b> ∪.∠	NEG		
Free Water 38:55) Rev: 1	scalar	Visual*	Co	ntact/Location:		



## **OIL ANALYSIS REPORT**





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0811312 : 02577259 : 5630319

Received Diagnosed : 21 Aug 2023 : 21 Aug 2023

Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

C.G. EQUIPMENT

7367 Wellington Rd. 30, Unit A Guelph, ON CA NOM 2TO

Contact: Maureen McDonald mmcdonald@cgequipment.com

F: (519)837-2055

T: