

PROBLEM SUMMARY

Area Direct Strip Mill/Finishing Machine Id SH7 HYDRAULIC SYSTEM (DSC010) (S/N 1000016488) Component

Hydraulic System

HOUGHTON HOUGHTO-SAFE 620 (15000 LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor. Please note that this is a corrected copy for data entry updates.

PROBLEMATIC TEST RESULTS								
Sample Status			ATTENTION	ABNORMAL	ABNORMAL			
Particles >4µm	ASTM D7647	>640	<u> </u>	305	306			
Particles >6µm	ASTM D7647	>160	🔺 215	147	147			
Oil Cleanliness	ISO 4406 (c)	>16/14/11	17/15/10	🔺 15/14/13	🔺 15/14/13			

Customer Id: ALGSSM Sample No.: WC0837456 Lab Number: 02586213 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com



RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component.		

HISTORICAL DIAGNOSIS

08 Aug 2023 Diag: Kevin Marson

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The pH level of this fluid is within the acceptable limits. The reserve alkalinity of this fluid is acceptable. The water concentration level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



Due to the low reserve alkalinity it is advised that you contact HOUGHTON to assist in restoring the proper amine concentration. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code. The reserve alkalinity of this fluid is lower than acceptable. The AN level is acceptable for this fluid. The pH level of this fluid is within the acceptable limits. The water concentration level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

15 May 2023 Diag: Kevin Marson

We recommend you service the filters on this component. Resample at the next service interval to monitor. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.Component wear rates appear to be normal (unconfirmed). There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The pH level of this fluid is within the acceptable limits. The reserve alkalinity of this fluid is acceptable. The water concentration level is acceptable for this fluid. The condition of the oil is suitable for further service.



iew repor

view report









OIL ANALYSIS REPORT

Direct Strip Mill/Finishing SH7 HYDRAULIC SYSTEM (DSC010) (S/N 1000016488) Component

Hydraulic System

HOUGHTON HOUGHTO-SAFE 620 (15000 LTR)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor. Please note that this is a corrected copy for data entry updates.

Wear

All component wear rates are normal.

Contamination

There is a light amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The pH level of this fluid is within the acceptable limits. The reserve alkalinity of this fluid is acceptable. The water concentration level is acceptable for this fluid. The condition of the oil is suitable for further service.



Oil Cleanliness

ISO 4406 (c)

>16/14/11 🔺

Contact/Location: Maintenance Technology - Algoma Reliability - ALGSSM

▲ 15/14/13

17/15/10

▲ 15/14/13



160 Alkal 140 Reserve 100

80

OIL ANALYSIS REPORT



FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		4.89	4.56	5.52
Alkiline Reserve (Oils)	ml KOH/g	ASTM D1121*	125	133	130	9 7
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	FRGLY	FRGLY	FRGLY
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>43.5	>10%	>10%	>10%
Free Water	scalar	Visual*		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
ρΗ	Scale 0-14	ASTM D1287*		9.37	9.56	9.21
Visc @ 40°C	cSt	ASTM D7279(m)		43.0	43.1	43.9
SAMPLE IMAGES	6	method	limit/base	current	history1	history2
Color						
Bottom						



0v3/71



: 02586213 Diagnosed : 13 Oct 2023 : 5655279 Diagnostician : Kevin Marson Test Package : IND 2 (Additional Tests: KF, pH, ReserveAlk, TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

: 02 Oct 2023

Received

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 ALGOMA STEEL INC. - STORES DEPT. 301 WALLACE TERRACE SAULT STE MARIE, ON CA P6C 1K8 Contact: Algoma Reliability algomareliability@algoma.com T: (705)206-1059 F: (705)945-3585

Report Id: ALGSSM [WCAMIS] 02586213 (Generated: 10/13/2023 14:43:21) Rev: 2

: WC0837456

Contact/Location: Maintenance Technology - Algoma Reliability - ALGSSM