

**OIL ANALYSIS REPORT** 

**Beneco - 888053 AG202** 

Component **Hydraulic System** 

**R&O OIL ISO 68 (--- GAL)** 

# Sample Rating Trend NORMAL

### Recommendation

This is a baseline read-out on the submitted sample.

### Wear

{not applicable}

## Contamination

{not applicable}

## **Fluid Condition**

{not applicable}

				Oct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Batch #		Client Info		AG202		
Machine ID		Client Info		Sales		
Department		Client Info		Drum		
Sample From		Client Info		Initial		
Production Stage		Client Info		10/04/2023		
Sample Number		Client Info		E30000471		
Sample Date		Client Info		03 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	0		
Chromium	ppm	ASTM D5185(m)	>20	0		
Nickel	ppm	ASTM D5185(m)	>20	0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)	>20	<1		
Lead	ppm	ASTM D5185(m)	>20	0		
Copper	ppm	ASTM D5185(m)	>20	<1		
Tin	ppm	ASTM D5185(m)	>20	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	5	<1		
Barium	ppm	ASTM D5185(m)	5	<1		
Molybdenum	ppm	ASTM D5185(m)	5	0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	5	0		
Calcium	ppm	ASTM D5185(m)	5	<1		
Phosphorus	ppm	ASTM D5185(m)	100	1		
Zinc	ppm	ASTM D5185(m)		1		
Sulfur	ppm	ASTM D5185(m)	1500	19		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	8	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	0		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	0		
Water	%	ASTM D6304*	>0.05	0.001		


ppm Water

ppm ASTM D6304\* >500

8.4



# OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: 02587160 : 5656226

Received : 05 Oct 2023 : E30000471 Diagnosed : 10 Oct 2023 Diagnostician : Tatiana Sorkina Test Package : IND 2 (Additional Tests: KF, KV100, TAN Man, VI)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

**Environmental 360 Solutions Ltd.** 640 Victoria Street

Cobourg, ON **CA K9A 5H5** Contact: Fred Kosseim fkosseim@e360s.ca

T: (905)372-2251 F: (905)372-1658