









COOLANT REPORT



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : CU0021779 **Received** : 11 Oct 2023
Lab Number : 02588423 **Diagnosed** : 11 Oct 2023
Unique Number : 5657489 **Diagnostician** : Wes Davis
Test Package : COOL

CUMMINS DIESEL
 50 SIMMONDS DRIVE
 DARTMOUTH, NS
 CA B3B 1R3
 Contact: Maurice Connolly
 maurice.connolly@cummins.com
 T: (902)468-7938
 F: (902)468-5177

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.