











# COOLANT REPORT



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 CUMMINS CANADA ULC - GENERATOR DIVISION  
**Sample No.** : CU0021216 **Received** : 16 Oct 2023 7175 PACIFIC CIRCLE  
**Lab Number** : 02589429 **Diagnosed** : 16 Oct 2023 MISSISSAUGA, ON  
**Unique Number** : 5658495 **Diagnostician** : Wes Davis CA L5T 2A5  
**Test Package** : COOL

Contact: Zaneef Abboobakar  
 zaneef.abboobakar@cummins.com  
 T: (905)795-0035  
 F: (905)795-0035

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.