

**FILTER DEBRIS ANALYSIS** 

Filter 5-3-230 - Recirc Filter

Component **Filter** 

**NOT GIVEN (--- GAL)** 

# Sample Rating Trend NORMAL

### Recommendation

Resample at the next service interval to monitor.

## **Wear Particles**

The filter contained no appreciable wear particles. All filter wear levels are normal.

# Contaminants

The filter contained only normal levels of contaminants, and debris. All filter contaminant levels are normal.

				Oct2023		
SAMPLE INFORMA	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		wc		
Sample Date		Client Info		16 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
FILTER WEAR PAR	TICLES	method	limit/base	current	history1	history2
Ferrous Rubbing	Scale 0-10	ASTM D7684*		1		
Ferrous Sliding	Scale 0-10	ASTM D7684*				
Ferrous Cutting	Scale 0-10	ASTM D7684*				
Ferrous Rolling	Scale 0-10	ASTM D7684*				
Ferrous Break-in	Scale 0-10	ASTM D7684*				
Ferrous Spheres	Scale 0-10	ASTM D7684*				
Ferrous Black Oxides	Scale 0-10	ASTM D7684*				
Ferrous Red Oxides	Scale 0-10	ASTM D7684*				
Ferrous Corrosive	Scale 0-10	ASTM D7684*				
Ferrous Other	Scale 0-10	ASTM D7684*				
Nonferrous Rubbing	Scale 0-10	ASTM D7684*		1		
Nonferrous Sliding	Scale 0-10	ASTM D7684*				
Nonferrous Cutting	Scale 0-10	ASTM D7684*				
Nonferrous Rolling	Scale 0-10	ASTM D7684*				
Nonferrous Other	Scale 0-10	ASTM D7684*				
FILTER CONTAMI	NANTS	method	limit/base	current	history1	history2
Sand/Dirt	Scale 0-10	ASTM D7684*		3		
Fibres	Scale 0-10	ASTM D7684*		2		
Spheres	Scale 0-10	ASTM D7684*				
Other	Scale 0-10	ASTM D7684*				
Patch Weight	mg	ASTM D7684*		129		
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
3ottom				no image	no image	no im





# **FILTER REPORT**

Filter
Machine Id
5-3-230 - Recirc Filter

Filter

**NOT GIVEN (--- GAL)** 





### WEAE

The filter contained no appreciable wear particles. All filter wear levels are normal.