



OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Area
[62639]
 Machine Id
VOLVO VNL740 4518

Component
Diesel Engine
 Fluid
PETRO CANADA DURON SAE 10W30 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition

The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC0869677	---	---
Sample Date	Client Info		13 Oct 2023	---	---
Machine Age	mths	Client Info	50	---	---
Oil Age	mths	Client Info	7	---	---
Oil Changed	Client Info		Changed	---	---
Sample Status			NORMAL	---	---

CONTAMINATION

	method	limit/base	current	history1	history2
Fuel	WC Method	>6.0	<1.0	---	---
Glycol	WC Method		NEG	---	---

WEAR METALS

	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m) >100	86	---	---
Chromium	ppm	ASTM D5185(m) >20	1	---	---
Nickel	ppm	ASTM D5185(m) >2	2	---	---
Titanium	ppm	ASTM D5185(m)	0	---	---
Silver	ppm	ASTM D5185(m) >2	<1	---	---
Aluminum	ppm	ASTM D5185(m) >25	6	---	---
Lead	ppm	ASTM D5185(m) >40	2	---	---
Copper	ppm	ASTM D5185(m) >330	6	---	---
Tin	ppm	ASTM D5185(m) >15	1	---	---
Antimony	ppm	ASTM D5185(m)	0	---	---
Vanadium	ppm	ASTM D5185(m)	0	---	---
Beryllium	ppm	ASTM D5185(m)	0	---	---
Cadmium	ppm	ASTM D5185(m)	0	---	---

ADDITIVES

	method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m) 1	3	---	---
Barium	ppm	ASTM D5185(m) 1	<1	---	---
Molybdenum	ppm	ASTM D5185(m) 1	60	---	---
Manganese	ppm	ASTM D5185(m) 1	<1	---	---
Magnesium	ppm	ASTM D5185(m) 10	923	---	---
Calcium	ppm	ASTM D5185(m) 2942	1150	---	---
Phosphorus	ppm	ASTM D5185(m) 1102	970	---	---
Zinc	ppm	ASTM D5185(m) 1351	1191	---	---
Sulfur	ppm	ASTM D5185(m) 3903	2090	---	---
Lithium	ppm	ASTM D5185(m)	<1	---	---

CONTAMINANTS

	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m) >25	8	---	---
Sodium	ppm	ASTM D5185(m)	3	---	---
Potassium	ppm	ASTM D5185(m) >20	2	---	---

INFRA-RED


	method	limit/base	current	history1	history2
Soot %	%	ASTM D7844* >3	1.1	---	---
Nitration	Abs/cm	ASTM D7624* >20	12.9	---	---
Sulfation	Abs/.1mm	ASTM D7415* >30	27.8	---	---

FLUID DEGRADATION

	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414* >25	25.9	---	---











OIL ANALYSIS REPORT



VISUAL	method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	NEG	---
Free Water	scalar	Visual*		NEG	---

FLUID PROPERTIES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	11.4	11.3	---

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 PERFORMANCE EQUIPMENT - VISION TRUCK
Sample No. : WC0869677 **Received** : 18 Oct 2023 415 EVANS AVENUE
Lab Number : 02589957 **Diagnosed** : 19 Oct 2023 ETOBICOKE, ON
Unique Number : 5659023 **Diagnostician** : Kevin Marson CA M8W 0B3
Test Package : MOB 1 Contact: Service

To discuss this sample report, contact Customer Service at 1-800-268-2131. etobservice@visiontruckgroup.com
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T:
 Validity of results and interpretation are based on the sample and information as supplied. F: