

# **OIL ANALYSIS REPORT**

Sample Rating Trend
ISO

# QUENCH HPU SIG P4

Component

**Hydraulic System** 

**NOT GIVEN (87 GAL)** 

## DIAGNOSIS

### Recommendation

This is a baseline read-out on the submitted sample.

#### Wear

{not applicable}

## Contamination

Oil Cleanliness are severely high. Particles >4 $\mu$ m are severely high. Particles >6 $\mu$ m are abnormally high. Particles >14 $\mu$ m are notably high.


#### **Fluid Condition**

{not applicable}

		1		Oct2023	<u> </u>	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0861010		
Sample Date		Client Info		17 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<b>7</b> 0915		
Particles >6µm		ASTM D7647	>1300	<b>9836</b>		
Particles >14µm		ASTM D7647	>160	<b>226</b>		
Particles >21µm		ASTM D7647	>40	51		
Particles >38µm		ASTM D7647	>10	3		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	23/20/15		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	VLITE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



## **OIL ANALYSIS REPORT**





**CALA** ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number : 5659230

: WC0861010

: 02590164

Validity of results and interpretation are based on the sample and information as supplied.

Received Diagnosed

: 18 Oct 2023 : 19 Oct 2023 Diagnostician : Kevin Marson

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 KLA HYDRAULIC SALES & SERVICE 43 Rockview Gardens Concord, ON CA L4K 2J4 Contact: Dave Ferraro

Test Package : TEST ( Additional Tests: PrtCount ) To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

dferraro4@hotmail.com T: (647)382-4668

Report Id: KLAALL [WCAMIS] 02590164 (Generated: 10/19/2023 09:35:26) Rev: 1

Contact/Location: Dave Ferraro - KLAALL