











# COOLANT REPORT



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **MANITOU LIN TRANSPORT (GARAGE)**  
**Sample No.** : WC0864504 **Received** : 20 Oct 2023 1335 SHAWSON DRIVE  
**Lab Number** : 02590788 **Diagnosed** : 22 Oct 2023 MISSISSAUGA, ON  
**Unique Number** : 5659854 **Diagnostician** : Kevin Marson CA L4W 1C4  
**Test Package** : COOL

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.  
 Contact: Patrick Morin  
 pmorin@manitoulintransport.com  
 T:  
 F: (905)564-6361