


# **OIL ANALYSIS REPORT**

Sample Rating Trend



NORMAL



# 517C RETAIN

Component

**Unknown Component** 

NOT GIVEN (--- GAL)

### Recommendation

This is a baseline read-out on the submitted sample.

### Wear

{not applicable}

### Contamination

{not applicable}


### **Fluid Condition**


{not applicable}

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PP		
Sample Date		Client Info		19 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				DECUNT.	no image	no image
Bottom					no image	no image



## **OIL ANALYSIS REPORT**







**CALA** ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number : 5659884

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : PP : 02590818

Received Diagnosed

: 26 Oct 2023 Diagnostician : Bill Quesnel

: 20 Oct 2023

Test Package : TEST ( Additional Tests: FT-IR )

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

WAKEFIELD CANADA INC.

3620 LAKESHORE BLVD WEST TORONTO, ON

CA M8W 1P2 Contact: Natalee Davis ndavis@wakefieldcanada.ca

T: (416)252-5511 F: (416)354-4515