


PROBLEM SUMMARY


Hydro Extrusions - S08200 A2310119

Component **Hydraulic System**

AW HYDRAULIC OIL ISO 46 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

This is a baseline read-out on the submitted sample.

PROBLEMATIC TEST RESULTS								
Sample Status			ATTENTION					
Particles >4µm	ASTM D7647	>5000	6077					
Oil Cleanliness	ISO 4406 (c)	>19/17/14	20/17/12					

Customer Id: CHECOB Sample No.: E30000571 Lab Number: 02590997 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Tatiana Sorkina +1 (800)263-3939 tsorkina@e360s.ca

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

Hydro Extrusions - S08200 A2310119

Component

Hydraulic System

AW HYDRAULIC OIL ISO 46 (--- GAL)



DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Wear

{not applicable}

Contamination

Particles $>4\mu m$ and oil cleanliness are notably high.

The sample submitted is 16 times dirtier than the Hydro Extrusion ISO dirt count requirement of 16/14/11.

Fluid Condition

{not applicable}

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Batch #		Client Info		A2310119		
Machine ID		Client Info		Sales		
Department		Client Info		Machine		
Sample From		Client Info		Initial		
Production Stage		Client Info		10/20/2023		
Sample Number		Client Info		E30000571		
Sample Date		Client Info		06 Sep 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2


WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	0		
Chromium	ppm	ASTM D5185(m)	>20	0		
Nickel	ppm	ASTM D5185(m)	>20	0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)	>20	0		
Lead	ppm	ASTM D5185(m)	>20	0		
Copper	ppm	ASTM D5185(m)	>20	<1		
Tin	ppm	ASTM D5185(m)	>20	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	5	<1		
Barium	ppm	ASTM D5185(m)	5	<1		
Molybdenum	ppm	ASTM D5185(m)	5	<1		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	25	15		
Calcium	ppm	ASTM D5185(m)	200	71		
Phosphorus	ppm	ASTM D5185(m)	300	307		
Zinc	ppm	ASTM D5185(m)	370	392		
Sulfur	ppm	ASTM D5185(m)	2500	635		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	3	method	limit/base	current	history1	history2

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	<1		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	0		
Water	%	ASTM D6304*	>0.05	0.003		
ppm Water	ppm	ASTM D6304*	>500	37.8		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number**

+02590997

: E30000571

Received Diagnosed : 5668076 Diagnostician

: 23 Oct 2023 : 25 Oct 2023

: Tatiana Sorkina

Test Package : IND 2 (Additional Tests: KF, KV100, VI) To discuss this sample report, contact Customer Service at 1-905-372-2251.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Environmental 360 Solutions Ltd. 640 Victoria Street

Cobourg, ON **CA K9A 5H5** Contact: Pierre Guillet

pguillet@e360s.ca T:

F: (905)373-4950

Contact/Location: Pierre Guillet - CHECOB