

# **OIL ANALYSIS REPORT**

[516951] 1944927

**Unknown Component** 

NOT GIVEN (--- GAL)

Sample Rating Trend



### Recommendation

This is a baseline read-out on the submitted sample.

### Wear

{not applicable}

### Contamination

ISO Cleanliness Code (ISO 4406:1999): 14/12/9; Cumulative particle counts  $>4\mu m = 119$ ,  $>6\mu m = 38$ ,  $>14\mu m = 4$ ,  $>21\mu m = 1$ ,  $>38\mu m = 0$ ,  $>71\mu m = 0$ .


### **Fluid Condition**

{not applicable}

				Oct2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PP		
Sample Date		Client Info		26 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
FLUID CLEANLII	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	119		
Particles >6µm		ASTM D7647	>1300	38		
Particles >14µm		ASTM D7647	>160	4		
Particles >21µm		ASTM D7647	>40	1		
Particles >38µm		ASTM D7647	>10	0		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	14/12/9		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
SAMPLE IMAGE	S	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



## **OIL ANALYSIS REPORT**





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number

: PP : 02592503 Unique Number : 5669582

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 27 Oct 2023 Diagnosed : 30 Oct 2023 Diagnostician : Kevin Marson

Test Package : TEST ( Additional Tests: PrtCount ) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

**TESTMARK LABORATORIES** 

6820 KITIMAT ROAD MISSISSAUGA, ON CA L5L 5T5

Contact: Mississauga Sample mississauga.oils@testmark.ca T: (905)821-1112