


OIL ANALYSIS REPORT

HIGH CREST [6100209810] PE6068T561954

Component

Diesel Engine

PETRO CANADA DURON HP 15W40 (--- GAL)



Recommendation

Resample at the next service interval to monitor.

Metal levels are typical for a new component breaking in.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

SAMPLE INFORM	ΙΔΤΙΩΝ	method	limit/base	current	history1	history2
	1/11/011		IIIIIIIIIII		•	
Sample Number		Client Info		WA0020735		
Sample Date	la u a	Client Info		29 Nov 2023		
Machine Age	hrs	Client Info		855		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Fuel		WC Method	>2.1	<1.0		
Water		WC Method	>0.21	NEG		
Glycol		WC Method		NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>51	3		
Chromium	ppm	ASTM D5185(m)	>11	0		
Nickel	ppm	ASTM D5185(m)	>5	0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>3	<1		
Aluminum	ppm	ASTM D5185(m)	>31	<1		
Lead	ppm	ASTM D5185(m)	>26	0		
Copper	ppm	ASTM D5185(m)	>26	<1		
Tin	ppm	ASTM D5185(m)	>4	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	2		
Barium	ppm	ASTM D5185(m)	0	<1		
Molybdenum	ppm	ASTM D5185(m)	60	56		
Manganese	ppm	ASTM D5185(m)	0	0		
Magnesium	ppm	ASTM D5185(m)	1010	942		
Calcium	ppm	ASTM D5185(m)	1070	996		
Phosphorus	ppm	ASTM D5185(m)	1150	960		
Zinc	ppm	ASTM D5185(m)	1270	1138		
Sulfur	ppm	ASTM D5185(m)	2060	2541		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>22	3		
Sodium	ppm	ASTM D5185(m)	>31	2		
Potassium	ppm	ASTM D5185(m)	>20	0		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	0		
Nitration	Abs/cm	ASTM D7624*	>20	4.7		
Sulfation	Abs/.1mm	ASTM D7415*	>30	17.6		



OIL ANALYSIS REPORT



FLUID DEGRADA	TION	method				history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	13.0		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
Emulsified Water	scalar	Visual*	>0.21	NEG		
Free Water	scalar	Visual*		NEG		
FLUID PROPERT	TES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.6	14.6		

Visc @ 100°C	cSt	ASTM D7279(m)	15.6	14.6	
GRAPHS					
Iron (ppm) 200 Severe 150 Abnormal			Nov29/23	Lead (ppm) Severe Abnormal 20 ECC/627/09/	Nov29/23
Aluminum (ppm) Severe Abnormal EZ/EZ/ADA			Nov29/23	Chromium (ppm) 25 20 Wils 10 Abnormal	Nov29/23
Copper (ppm) Severe Abnormal EZ/6Z/AON			Nov29/23	Silicon (ppm) 40 Severe Abnormal	Nov29/23
Viscosity @ 100°C			Nov29/23	Soot % 6.0 Severe Abnormal 82 4.0 Abnormal	Nov2973



CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number : 5693925

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WA0020735 : 02600840

Received Diagnosed

: 05 Dec 2023 : 05 Dec 2023 Diagnostician : Wes Davis

Test Package : MOB 1 (Additional Tests: Visual) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Wajax Power Systems 70 Raddall Avenue Dartmouth, NS

CA B3B 1T7 Contact: Holly Hinton hhinton@wajax.com

F: (902)468-3325