


OIL ANALYSIS REPORT

Area [5612] **NOVA 1603**

Component **Diesel Engine**

VALVOLINE 15W40 (--- GAL)





Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition


The condition of the oil is acceptable for the time in service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0875092	WC0858043	WC0843557
Sample Date		Client Info		24 Nov 2023	23 Oct 2023	28 Sep 2023
Machine Age	kms	Client Info		598991	589807	580873
Oil Age	kms	Client Info		0	0	0
Oil Changed		Client Info		Changed	N/A	Changed
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>100	8	8	9
Chromium	ppm	ASTM D5185(m)	>20	<1	<1	<1
Nickel	ppm	ASTM D5185(m)	>4	<1	<1	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)	>3	<1	<1	<1
Aluminum	ppm	ASTM D5185(m)	>20	1	1	2
Lead	ppm	ASTM D5185(m)	>40	0	0	<1
Copper	ppm	ASTM D5185(m)	>330	2	3	4
Tin	ppm	ASTM D5185(m)	>15	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	39	13	11	14
Barium	ppm	ASTM D5185(m)	1	<1	<1	<1
Molybdenum	ppm	ASTM D5185(m)	49	10	10	17
Manganese	ppm	ASTM D5185(m)	1	0	0	0
Magnesium	ppm	ASTM D5185(m)	616	60	42	49
Calcium	ppm	ASTM D5185(m)	1554	2258	2287	2288
Phosphorus	ppm	ASTM D5185(m)	899	845	867	898
Zinc	ppm	ASTM D5185(m)		1009	1032	1052
Sulfur	ppm	ASTM D5185(m)	2624	2895	2947	2962
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	3	4	4
Sodium	ppm	ASTM D5185(m)		1	2	2
Potassium	ppm	ASTM D5185(m)	>20	<1	0	0
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	0.2	0.2	0.2
Nitration	Abs/cm	ASTM D7624*	>20	7.6	7.8	8.4
Sulfation	Abs/.1mm	ASTM D7415*	>30	19.5	19.7	20.9



OIL ANALYSIS REPORT








FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	12.7	13.1	15.3
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>0.2	NEG	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG	NEG


					•	•
Visc @ 100°C	cSt	ASTM D7279(m)	13.6	12.7	13.0	13.1
CDADUC						


200 - Sev	ere	1 1 1						
150 - Abr	normal							
50-								
0	12	7	- F	- I		20	23	72
0 19/16	Мау6,	Nov3,	Apr19/	Dec28/	Jul21/	Dec11/	Feb16/	77 July 24 / 2
	ıminu	/						



















CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WC0875092 : 02601192 : 5694277

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received

: 06 Dec 2023 Diagnosed : 06 Dec 2023 Diagnostician : Wes Davis

Test Package : MOB 1 (Additional Tests: Visual)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

MVT Canadian Bus 133 Welham Road Barrie, ON

CA L4N 8Y3 Contact: Frank Mastromarco frank.mastromarco@mvtransit.com T: (709)792-5033

F: