

OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL





Bank of Montreal Comp.Ctr.#1 [357181] Machine Id TRANE L79F-01796

Component Chiller Fluid

TRANE 0022 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GTT0000922	GTT43617	
Sample Date		Client Info		04 Dec 2023	31 Mar 2023	
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A	N/A	
Sample Status				NORMAL	NORMAL	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>8	0	<1	
Chromium	ppm	ASTM D5185(m)	>2	0	<1	
Nickel	ppm	ASTM D5185(m)		<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>2	<1		
Aluminum	ppm	ASTM D5185(m)	>3	0	<1	
Lead	ppm	ASTM D5185(m)	>2	0	<1	
Copper	ppm	ASTM D5185(m)	>8	<1	<1	
Tin	ppm	ASTM D5185(m)	>4	<1	<1	
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1		
Barium	ppm	ASTM D5185(m)	0	<1		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)	0	0		
Magnesium	ppm	ASTM D5185(m)	0	0		
Calcium	ppm	ASTM D5185(m)	0	0		
Phosphorus	ppm	ASTM D5185(m)	35	4		
Zinc	ppm	ASTM D5185(m)	0	<1	<1	
Sulfur	ppm	ASTM D5185(m)	30	52		
Lithium	ppm	ASTM D5185(m)		1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	8		
Sodium	ppm	ASTM D5185(m)		4		
Potassium	ppm	ASTM D5185(m)	>20	10		
ppm Water	ppm	ASTM D6304*	>50	13	9	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.05	0.01	0.003	



OIL ANALYSIS REPORT

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	47	38.5		
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image
				The second second		



Report Id: GTT0000257 [WCAMIS] 02602976 (Generated: 12/15/2023 17:13:52) Rev: 1

Sample No. : GTT0000922 Recieved : 13 Dec 2023 Lab Number : 02602976 Diagnosed : 15 Dec 2023 Unique Number : 5696061 Diagnostician : Bill Quesnel

Test Package : IND 2 (Additional Tests: KV40) Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-905-847-9300 Ext 26.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Damages: Seller shall in no event be liable for special, incidental, or consequential damages, of a commercial nature, resulting from any cause.

Modern Niagara Building Services

8125 Hwy 50 Vaughan, ON CA L4H 4S6

T:

F: