

## FUEL REPORT

Sample Rating Trend

### INTERIOR HEALTH [180016453] Machine Id MTU 5352011804

Component Diesel Fuel

Fluid No.2 DIESEL FUEL (ULTRALOW SULPHUR) (--- GAL)

#### DIAGNOSIS

#### Recommendation

Please contact your representative for information regarding the proper sampling kits for your service.

#### Corrosion

{not applicable}

#### Contaminants

There is no indication of any contamination in the component(unconfirmed).

### **Fuel Condition**

Not enough sample submitted to determine fuel condition and/or classification.

	Nov2023					
rear and that						




NORMAL

SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		VPA055674		
Sample Date		Client Info		21 Nov 2023		
Machine Age	hrs	Client Info		632		
Sample Status				NORMAL		
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	3.0	2.2		
SULFUR CONTER	١T	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185(m)	10	4		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	<1.0	0		
Sodium	ppm	ASTM D5185(m)	<0.1	0		
Potassium	ppm	ASTM D5185(m)	<0.1	2		
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185(m)	<0.1	0		
Nickel	ppm	ASTM D5185(m)	<0.1	0		
Lead	ppm	ASTM D5185(m)	<0.1	0		
Vanadium	ppm	ASTM D5185(m)	<0.1	0		
Iron	ppm	ASTM D5185(m)	<0.1	<1		
Calcium	ppm	ASTM D5185(m)	<0.1	0		
Magnesium	ppm	ASTM D5185(m)	<0.1	<1		
Phosphorus	ppm	ASTM D5185(m)	<0.1	<1		
Zinc	ppm	ASTM D5185(m)	<0.1	0		
SAMPLE IMAGES	\$	method	limit/base	current	history1	history2
Color					no image	no image
Bottom				(the second	no image	no image





# **FUEL REPORT**

#### Viscosity @ 40°C



#### Gas Chromatography (GCD)





: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 CULLEN DIESEL POWER - 695335 Laboratory CALA Sample No. : VPA055674 Recieved : 15 Dec 2023 9300 192 ST Lab Number : 02603639 Diagnosed : 18 Dec 2023 SURREY, BC ISO 17025:2017 Accredited Laboratory Unique Number : 5696724 Diagnostician : Kevin Marson CA V4N 3R8 Test Package : MOB 1 (Additional Tests: GC-PercFuel, GCD) Contact: Shane sdf@cullendiesel.com To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: (250)427-8271 Validity of results and interpretation are based on the sample and information as supplied. F: