




OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id
BULK TANK - PLANT 2
 Component
Bulk Tank New (Unused) Oil
 Fluid
PETRO CANADA ATF D3M (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Wear

{not applicable}

Contamination

The system cleanliness is acceptable for your target ISO 4406 cleanliness code.

Fluid Condition



{not applicable}

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number	Client Info			WC0885991	WC0604318	---
Sample Date	Client Info			13 Dec 2023	13 Oct 2023	---
Machine Age	hrs	Client Info		0	0	---
Oil Age	hrs	Client Info		0	0	---
Oil Changed	Client Info			N/A	N/A	---
Sample Status				NORMAL	NORMAL	---

CONTAMINATION		method	limit/base	current	history1	history2
Water	WC Method			NEG	NEG	---



FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647	>40000		731	433	---
Particles >6µm	ASTM D7647	>2500		148	117	---
Particles >14µm	ASTM D7647	>80		10	11	---
Particles >21µm	ASTM D7647	>20		4	3	---
Particles >38µm	ASTM D7647	>4		1	1	---
Particles >71µm	ASTM D7647	>3		0	1	---
Oil Cleanliness	ISO 4406 (c)	>22/18/13		17/14/10	16/14/11	---

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	---
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	---
Precipitate	scalar	Visual*	NONE	NONE	NONE	---
Silt	scalar	Visual*	NONE	NONE	NONE	---
Debris	scalar	Visual*	NONE	NONE	NONE	---
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	---
Appearance	scalar	Visual*	NORML	NORML	NORML	---
Odor	scalar	Visual*	NORML	NORML	NORML	---


SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				<i>no image</i>		<i>no image</i>
Bottom				<i>no image</i>		<i>no image</i>



OIL ANALYSIS REPORT



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0885991
Lab Number : 02603656
Unique Number : 5696741
Test Package : TEST (Additional Tests: PrtCount)

Skyjack - Plant 2 (div of Linamar)
 201 Woodlawn Rd. W.
 Guelph, ON
 CA N1H 1B8
 Contact: Paraschiva Nae
 paraschiva.nae@skyjack.com
 T: (519)837-0888
 F: (519)837-4895

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.