

# **OIL ANALYSIS REPORT**

# Signature Alum - A02500 A2312075

Component **Hydraulic System** 

**AW HYDRAULIC OIL ISO 68 (--- GAL)** 



#### Recommendation

This is a baseline read-out on the submitted sample.

#### Wear

Aluminum, copper and iron ppm levels are noted.

### Contamination

{not applicable}

### **Fluid Condition**

{not applicable}

				Dec2023		
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Batch #		Client Info		2023 12 0080		
Department		Client Info		Production		
Sample From		Client Info		Machine		
Production Stage		Client Info		Initial		
Sent to WC		Client Info		12/14/2023		
Sample Number		Client Info		E30000934		
Sample Date		Client Info		14 Dec 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINATION	J	method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	57		
Chromium	ppm	ASTM D5185(m)	>10	<1		
Nickel	ppm	ASTM D5185(m)	>10	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)	>10	137		
Lead	ppm	ASTM D5185(m)	>20	5		
Copper	ppm	ASTM D5185(m)		41		
Tin	ppm	ASTM D5185(m)	>10	<1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	5	6		
Barium	ppm	ASTM D5185(m)		2		
Molybdenum	ppm	ASTM D5185(m)	5	0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	25	4		
Calcium	ppm	ASTM D5185(m)		47		
Phosphorus	ppm	ASTM D5185(m)	300	405		
Zinc	ppm	ASTM D5185(m)		270		
Sulfur	ppm	ASTM D5185(m)	2500	1283		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	7		
Sodium	ppm	ASTM D5185(m)		1		
Potassium	ppm	ASTM D5185(m)	>20	<1		



## **OIL ANALYSIS REPORT**

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	MODER		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image
GRAPHS						



CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number : 5697050

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : E30000934 : 02603965

Validity of results and interpretation are based on the sample and information as supplied.

Recieved Diagnosed

: 18 Dec 2023 : 19 Dec 2023

Test Package : TEST ( Additional Tests: Bottom, ICP )

Diagnostician : Tatiana Sorkina

CA K9A 5H5 Contact: Tatiana Sorkina tsorkina@e360s.ca T: (800)263-3939 F: (905)373-4950

640 Victoria Street

Cobourg, ON

**Environmental 360 Solutions Ltd.** 

To discuss this sample report, contact Customer Service at 1-905-372-2251. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Report Id: CHECOB [WCAMIS] 02603965 (Generated: 12/19/2023 12:19:18) Rev: 1

Contact/Location: Tatiana Sorkina - CHECOB