




OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Area
ONTATI
 Machine Id
Silo #1 Gate 008 A

Component
Gearbox
 Fluid
FUCHS RENOLIN CLP ISO 220 (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Wear

{not applicable}

Contamination

{not applicable}

Fluid Condition

{not applicable}

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC0831853	WC0365364	---
Sample Date	Client Info		10 Jul 2023	10 Jul 2019	---
Machine Age	hrs	Client Info	0	0	---
Oil Age	hrs	Client Info	0	0	---
Oil Changed	Client Info		N/A	N/A	---
Sample Status			NORMAL	NORMAL	---





CONTAMINATION

	method	limit/base	current	history1	history2
Water	WC Method	>0.2	NEG	NEG	---

VISUAL

	method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	---
Yellow Metal	scalar	Visual*	NONE	NONE	---
Precipitate	scalar	Visual*	NONE	NONE	---
Silt	scalar	Visual*	NONE	NONE	---
Debris	scalar	Visual*	NONE	VLITE	---
Sand/Dirt	scalar	Visual*	NONE	NONE	---
Appearance	scalar	Visual*	NORML	NORML	---
Odor	scalar	Visual*	NORML	NORML	---

SAMPLE IMAGES

	method	limit/base	current	history1	history2
Color					no image
Bottom					no image



OIL ANALYSIS REPORT

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0831853 **Recieved** : 19 Dec 2023
Lab Number : 02604287 **Diagnosed** : 20 Dec 2023
Unique Number : 5697372 **Diagnostician** : Kevin Marson
Test Package : TEST

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

WEARCHECK CANADA INC.
 C8-1175 Appleby Line
 BURLINGTON, ON
 CA L7L 5H9
 Contact: Dorian Anderson
 dorian.anderson@wearcheck.com
 T:
 F: (905)569-8605